

Vicenza, 24th January, 2017

TECHNICAL INFO NO. 15: NEW VERSION OF THE FIRMWARE 1.34 FOR SMART ExR

Dear Partner

We kindly inform you that is now available on our Reserved Area the New Version of the Firmware 1.34 for Smart ExR ECU.

The 1.34 SMART ExR FW will solve:

- **Gas drive injectors error**, which is saved in gas detection and has appeared sporadically
- **Incorrect management of extra injection**, which may produce hesitations during acceleration in cold engine condition and during special management of extra injections.

In order to enable the new strategies, after having inserted the new firmware, it is important to **RESET** the ECU from the software.

We kindly remember you that it is fundamental to update always ECU's firmware and software and that the technical info are confidential and limited to Lovato Gas Installers and Distributors

If you need more information, please contact our **Technical Assistance Service**.